

Inner 3 Rows Area

HR100

MOTION & PRESENCE SENSOR

LOT No.

Power Supply : AC/DC12~24V±10% 50/60Hz
 Output Contact : Form C Relay
 DC50V 0.1A(Resistor Load)FAIL SAFE MODE
 Wiring : RED&BLACK(Power),WHITE(Common)
 YELLOW(Closed During Detection)
 GREEN(Open During Detection)
 MADE IN JAPAN

Sensitivity

Monitor Mode
 Normal
 Snow

Inner 3 Rows Presence Timer
 2s
 15s
 60s
 ∞
 1 2

WIDTH

Narrow Wide

Inner 3 Rows Area

Frequency
 A C
 B D
 7 8 7 8

Quantity of Rows
 R5 R3
 R4 R2
 5 6 5 6

Outer 2 Rows Presence Timer
 2s
 15s
 3

WIDTH

Narrow Wide

Outer 2 Rows Area

Outer 2 Rows Area